

HDCVI Recorder Firmware Release Notes

Firmware version:

DH_HCVR5x08-S2_Eng_P_V3.200.0004.11.R.20170417

DH_HCVR5x08-S2_SpnEng_NP_V3.200.0004.11.R.20170417

General_HCVR5x08-S2_Eng_PN_V3.200.0004.11.R.20170417

Applicable models:

HCVR5108C-V2, HCVR5108HC-V2, HCVR5108H-V2, HCVR5108HE-V2
HCVR5204A-V2, HCVR5204L-V2, HCVR5208A-V2, HCVR5208L-V2, HCVR5404L-V2, HCVR5408L-V2,
HCVR5804S-V2, HCVR5808S-V2
HCVR4116HS-S2, HCVR4116HE-S2, HCVR4216AN-S2, HCVR4216A-S2, HCVR4416L-S2, HCVR4816S-S2,
HCVR5108C-S2, HCVR5108H-S2, HCVR5108HE-S2, HCVR5204A-S2, HCVR5208A-S2
HCVR7104C-V2, HCVR7104HC-V2, HCVR7104H-V2, HCVR7104HE-V2, HCVR7204A-V2
HCVR7104C-S2, HCVR7104H-S2, HCVR7104HE-S2, HCVR7204A-S2

Optimizations & bug fixes:

1. Repair 88888 account CGI landing security issues;
2. Boot wizard P2P interface string changes;
3. Dual backup function has been incorporated;
4. telnet has been removed;
5. Fix the issue of flash program written;

Recommended tools version:

SmartPss	DH_Smart-PSS_ChnEng_IS_V1.11.2.R.20150327
NKB3000	General_NETKB3000_Chn_P_V2.610.0000.3.R.20141217
NKB1000	General_NETKB1000_ChnEng_V2.610.0000.4.R.20161024
DSS7016	General_DSS7000_Chn_Basic_V3.11.001.R.20150312
NetSDK	General_NETKB3000_Chn_P_V2.610.0000.3.R.20141217
ConfigTool	ConfigTool:DH_ConfigTool_Chn_V3.00.0.R.150303
DMSS	iOS-V3.31, Android-3.00