

HDCVI Recorder Firmware Release Notes

Firmware version:

DH_HCVR5x16-S2_Eng_P_V3.200.0004.11.R.20170417

DH_HCVR5x16-S2_SpnEng_NP_V3.200.0004.11.R.20170417

General_HCVR5x16-S2_Eng_PN_V3.200.0004.11.R.20170417

Applicable models:

HCVR5116HC-V2, HCVR5116H-V2, HCVR5116HE-V2, HCVR5216A-V2, HCVR5216L-V2 HCVR5416L-V2, HCVR5816S-V2 HCVR5116H-S2, HCVR5116HE-S2, HCVR5216A-S2, HCVR5216AN-S2 HCVR7108H-V2, HCVR7108HC-V2, HCVR7108HE-V2, HCVR7208A-V2 HCVR7108H-S2, HCVR7108HE-S2, HCVR7208A-S2

Optimizations & bug fixes:

1. Repair 88888 account CGI landing security issues;
2. Boot wizard P2P interface string changes;
3. Dual backup function has been incorporated;
4. telnet has been removed;
5. Fix the issue of flash program written;

Recommended tools version:

SmartPss	DH_Smart-PSS_ChngEng_IS_V1.11.2.R.20150327
NKB3000	General_NETKB3000_Chng_P_V2.610.0000.3.R.20141217
NKB1000	General_NETKB1000_ChngEng_V2.610.0000.4.R.20161024
DSS7016	General_DSS7000_Chng_Basic_V3.11.001.R.20150312
NetSDK	General_NETKB3000_Chng_P_V2.610.0000.3.R.20141217
ConfigTool	ConfigTool:DH_ConfigTool_Chng_V3.00.0.R.150303
DMSS	iOS-V3.31, Android-3.00